Diamond Head Oil NEW JERSEY EPA ID# NJD092226000



EPA REGION 2

CONGRESSIONAL DIST. 13 Hudson County

Kearny

Site Description -

The Diamond Head Oil site is located at 1401 Harrison Avenue in Kearny, New Jersey. The site, an oil reprocessing facility, was in operation from February 1, 1946 to early 1979. Currently the site is inactive and consists of approximately 15 acres of vacant land. The site is comprised of wetland areas and drainage ditches, a small wetland/pond, a vegetated landfill area along the western border of the site, and remnants of the former Diamond Head Oil Refinery on the eastern portion of the site. During facility operations, two above-ground storage tanks and possibly underground pits were used to store oily wastes. These wastes were intermittently discharged directly to adjacent properties, including the wetland area to the south of the site, creating an "oil lake". The abandoned refinery portion of the site contains various construction debris, including foundations of the former on-site building and two former above-ground storage tanks.


Site Responsibility: This site is being addressed through Federal actions.

NPL LISTING HISTORY

Proposed Date: 07/27/00 Final Date: 09/05/02

Threats and Contaminants







Cleanup Approach

The site is being addressed through a long-term remedial phase directed at cleanup of the entire site.

Response Action Status _____



Initial Actions: The New Jersey Department of Transportation (NJDOT) acquire the property south of the site in 1968. In 1977, NJDOT began construction of I-280 and was reported to have removed nine million gallons of oil-contaminated water and five to six million cubic yards of oily sludge from the "lake". In addition, approximately 7,500 gallons of material

were pumped out of the tanks and disposed of off site. Twenty-seven tons of contaminated soil were also removed in 1982.



Entire Site: Previous investigations include a sampling event conducted by the New Jersey Department of Environmental Protection, an Environmental Site Characterization, and a Site Inspection conducted by EPA's Region II Field Investigation Team. In December 1999,

EPA conducted an Expanded Site Inspection (ESI) at the site. During the ESI, EPA collected surface/subsurface, soil and ground water samples from 20 borings advanced throughout the site. Several on-site monitoring wells had a layer of non-aqueous phase liquid on top of the water column. EPA also collected sediment samples from the on-site wetland/pond area as well as from the wetland area extending along the southern perimeter of the site.

Cleanup Progress



EPA is presently performing a Remedial Investigation and Feasibility Study (RI/FS) at the site, to select a remedy to eliminate, reduce, or control risks to human health and the environment.